







Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /  
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /  
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /  
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb  
 / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /  
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu



Position



- 1 = A 963 131 NU
- 4 = A 963 132 NU
- 8 = A 963 143 NU
- 9 = A 963 146 NU
- 10 = A 963 147 NU
- 13 = A 963 132 NU



**EASY BOX**  
 A 1000 NU






1214 / A 866 090 40  
 Made in Germany



Ideal Standard International BVBA  
 Corporate Village - Gent Building  
 Da Vincilaan 2  
 1935 Zaventem  
 Belgium

[www.idealstandardinternational.com](http://www.idealstandardinternational.com)





**P**  
Prüfdruck  
bar

MAX. 16

<b>P</b> bar	MAX. 10 0,5	5 1	thumbs up
<b>T</b> °C	MAX. 80	65 40	thumbs up